CRITICAL ITEMS LIST (CIL)

SYSTEM:

ASI

Electrical Cable Trays

FUNCTIONAL CRIT: PHASE(S):

Ь

SUBSYSTEM: REV & DATE: DCN & DATE:

J, 12-19-97

ANALYSTS:

J. Hicks/E. Howell

HAZARD REF:

\$.11

FAILURE MODE:

Structural Failure

FAILURE EFFECT:

Loss of mission and vehicle/crew due to ET structural failure or debris source to

Orbiter from cover.

TIME TO EFFECT:

Immediate

FAILURE CAUSE(S):

A: Improper Manufacture

Failure of Attaching Hardware

REDUNDANCY SCREENS:

Not Applicable

FUNCTIONAL DESCRIPTION: Cover for fairing between RH SRB and RH vertical strut trays.

EFFECTIVITY PART NAME QTY FMEA ITEM PART NO. CODE(S) 1 LWT-54 & Up 4.3.97.1 80911041128-001 Cable Tray Cover

REMARKS:

CRITICAL ITEMS LIST (CIL) CONTINUATION SHEET

SYSTEM:

ASI

SUBSYSTEM: FMEA ITEM CODE(S): Electrical Cable Trays

REV & DATE: DCN & DATE: J, 12-19-97

4.3.97.1

RATIONALE FOR RETENTION

DESIGN:

- A, B: The cable tray cover is machined from 2219-T87 aluminum alloy sheet stock. Materials selected for this part number are in accordance with MMC-ET-SE16 which assures repetitive conformance of composition and properties.
- A: The cover is designed to the required yield (1.1) and ultimate (1.4) safety factors (ET Stress Report 826-2188).
- B: The attaching hardware is selected from the Approved Standard Parts List (ASPL 826-3500). The hardware is installed per STP2014 and torqued using values specified on Engineering drawings. Tensile installation loads are sufficient to provide screening for major flaws in individual fasteners.

TEST:

The Cable Tray Cover is certified. Reference HCS MMC-ET-TMO8-L-S056 (LWT-54 thru 88) and HCS MMC-ET-TMO8-L-S517 (LWT-89 & Up).

Vendor:

B: Attaching fasteners are procured and tested to standard drawings 26L3 and 34L1.

INSPECTION:

Vendor Inspection-Lockheed Martin Surveillance:

- A, B: Verify materials selection and verification controls (MMC-ET-SE16, drawing 80911041128 and standard drawings 26L3 and 34L1).
- A: Inspect dimensional conformance (drawing 80911041128).

MAF Quality Inspection:

- B: Inspect that attaching hardware is free from damage (drawing 80911041149 and STP2014).
- A, B: Verify installation and witness torque (drawing 80911041149 and STP2014).
- B: Verify locking feature (drawing 80911041149 and STP2014).

FAILURE HISTORY:

Current data on test failures, unexplained anomalies and other failures experienced during ground processing activity can be found in the PRACA data base.